



JON M. HUNTSMAN, JR.
Governor


GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
April 6, 2011

Reviewed: 

Mine Name: County Canyon Shale	Permit Number: M/023/0024
Operator Name: Ash Grove Cement Company	Inspection Date: April 5, 2011
Inspector(s): Wayne Western	Time: 5:10 – 5:30 PM
Other Participants: None	Mine Status: ACT

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The bond amount is \$144,500.00 escalated till July 19, 2012. The permit fees are current.

The shale has been mined and stockpiled on site. The mine not being actively mined and only will be excavated in a downward direction (the floor of the mine will be lowered) having met the boundary of the deposit.


Directions to Site:

The site sits west of Nephi on Route 132 route (1812) east of the town of Leamington. Turn off is approximately 4.3 mile west of turn off onto 1812. Follow well kept road.

Conclusions and Recommendations:

The Division should continue to monitor the site.

Inspector's Signature

A handwritten signature in blue ink, appearing to read "Wayne Winters", is written over a horizontal line.

WHW:

cc: (OPERATOR)

Jerry Mansfield BLM

O:\M023-Juab\M0230024-CountyCanyon\Inspection\Insp-04052011.doc



Shale stockpile



Pit



Stockpile



Looking east